

SAFETY RECALL

ENTRAPMENT AND STRANGULATION HAZARD Simplicity Drop-side Cribs



Due to sizing problems with the crib's hardware, the drop-side can come off the tracks. When the drop-side detaches or partially detaches, it creates a hazardous gap, which can lead to infant entrapment and suffocation. There have been no injuries.

Manufacturer's Model Numbers

8620	8755	8810
8745	8756	8994
8748	8778	

Manufacturer's Code

This recall includes **ONLY** those units with a manufacturer's code ending with:

05DH	06GB
05GB	07DH
06DH	07GB

Model Number and Manufacturing Code can be found on headboard or footboard of the crib.

Sold from 2005 through August 2008 for around \$100 to \$300

Customers should **STOP** using this product **IMMEDIATELY** and return the product to the store where purchased for a refund or store credit.

For additional information, contact:

Recall Hotline at 800-858-8323

Between 9:30 a.m. to 5 p.m. Monday through Friday

or visit www.simplicityforchildren.com